## SAFETY MANAGEMENT CERTIFICATE

Certificate No: **n1181405-vpe** DNV GL Id No: **G116473** Date of issue:

2018-07-17

DNV.GL

Issued under the provisions of the INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA, 1974, as amended under the authority of the Government of

## THE REPUBLIC OF THE MARSHALL ISLANDS

	by <b>DNV GL</b>	
Particulars of Ship		
Name of Ship:	BALAO	
Distinctive Number or Letters:	5057	
Port of Registry:	MAJURO	
Type of Ship <sup>1</sup> :	Other cargo ship	
Gross Tonnage:	26412	
IMO Number:	9603594	
Particulars of Company <sup>2</sup>		
Company Name:	Klaveness Ship Management AS	
Company Address:	Drammensveien 260 0283 OSLO NORWAY	
Company Identification Number:	5602215	
This is to certify:		

that the safety management system of the ship has been audited and that it complies with the requirements of the International Management Code for the Safe Operation of Ships and for Pollution Prevention (ISM Code), following verification that the Document of Compliance for the Company is applicable to this type of ship.

This Safety Management Certificate is valid until **2023-08-24**, subject to periodical verification and the validity of the Document of Compliance remaining valid.

Completion date of audit on which this Certificate is based: 2018-07-17

## Issued at Seattle, Washington, United States on 2018-07-17



## for **DNV GL**

This document is signed electronically in accordance with IMO FAL.5/Circ.39/Rev.2. Validation and authentication can be obtained from trust.dnvgl.com by using the Unique Tracking Number (UTN): n1181405-vpe and ID: G116473

> Hassan Ramezanpoor Surveyor

<sup>1</sup> Insert the standard IMO ship type.

<sup>2</sup> See paragraph 1.1.2 of the ISM Code.



Form code: ISMV 101 UTN: n1181405-vpe Revision: 2018-02 www.dnvgl.com Page 1 of 3 © DNV GL 2014. DNV GL and the Horizon Graphic are trademarks of DNV GL AS.

Certificate No: **n1181405-vpe** Date of issue: **2018-07-17** 

Endorsement for inte	mediate verificat	ion
		regulation IX/6.1 of the Convention and paragraph n was found to comply with the requirements of the
Intermediate Verification (to be completed between the second and third anniversary date)	Place:	Date:
Stamp		Signature: Auditor, DNV GL
Additional verification	ו (if required)	A
Additional verification*:	Place:	Date:
		Signature:
Stamp		Auditor, DNV GL
Additional verification*:	Place:	Date:
		Signature:
Stamp		Auditor, DNV GL
Additional verification*:	Place:	Date:
		Signature:
Stamp	the velocient ever initians of each	Auditor, DNV GL
<i>Implementation of the International S A.1071(28).</i>	Safety Management (ISM) Code	cation has been completed and part B
13.13 of the ISM Code		• •
The ship complies with the re Certificate should, in accorda until		t B of the ISM Code, and the the ISM Code, be accepted as valid
	Place:	Date:
		Signature:
Stamp		Auditor, DNV GL

Certificate No: **n1181405-vpe** Date of issue: **2018-07-17** 

Endorsement to extend the validity of th of verification where part B 13.12 of the grace where part B 13.14 of the ISM cod	ISM code applies or for a period of
This Certificate should, in accordance with part B 13.12 be accepted as valid until	2 or part B 13.14 of the ISM Code,
Place:	Date:
Stamp	Signature:Auditor, DNV GL